
Main Cross Sections
Elastic
Capture
Inelastic
cross section (barn)
neutron energy(eV)
10^3
10^2
10^1
10^0
10^-1
10^-2
10^-3
10^-4
10^-5
10^-6
10^-5 10^-4 10^-3 10^-2 10^-1 10^0 10^1 10^2 10^3 10^4 10^5 10^6 10^7 10^8


Cross Section
cross section (barn)
neutron energy(eV)
*10^6
n_2n
n_na
n_np
n_n_1
n_n_2
n_n_3
n_n_4


Cross Section
cross section (barn)
neutron energy(eV)
*10^6
n_n_5
n_n_6
n_n_7
n_n_cont
n_n_tot
n_p_tot
n_d_tot
10^0
10^-1
10^-2
10^-3
10^-4
10^-5
10^-6
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20


Cross Section
n_a_tot
cross section (barn)
10^{-1}
10^{-2}
10^{-3}
10^{-4}
10^{-5}
10^{-6}
0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20
*10^{6}
neutron energy(eV)


Angular distribution (CMS)
Elastic
probability
10^{1}
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_2n part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_2n part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
14
16
18
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_na part.=neutron
probability
10^0
1.0 0.5 0.0 -0.5 -1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_na part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_na part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_np part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_np part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_np part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_1
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_2
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_3
probability
10^{0}
10^{-1}
1.0
0.5
0.0
-0.5
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_4
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_5
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_6
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (CMS)
n_n_7
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_n_cont part.=neutron
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_n_cont part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_p_tot part.=proton
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_p_tot part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_a_tot part.=alpha
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Angular distribution (LABS)
n_a_tot part.=gamma
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_2n part.=neutron
probability
10^{0}
10^{-2}
0
2
4
6
8
*10 6
energy (eV)
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_2n part.=gamma
probability
10^{2}
10^{1}
10^{0}
10^{-1}
0
2
4
6
8
*10 6
energy (eV)
14
16
18
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_na part.=neutron
probability
10^{1}
10^{-1}
0
2
4
6
8
*10 6
energy (eV)
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_na part.=alpha
probability
10^{1}
10^{0}
10^{-1}
0
5
10
15
energy (eV)
*10^6
5
10
15
20
neutron energy (eV)
*10^6


Energy distribution (LABS)
n_na part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
2
4
6
*10^6
energy (eV)
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_np part.=neutron
probability
10^{1}
10^{-1}
0
5
10
15
energy (eV)
*10^6
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_np part.=proton
probability
10^{1}
10^{-1}
0
energy (eV)
5
10
15
*10^6
10
15
neutron energy (eV)
20
*10^6


Energy distribution (LABS)
n_np part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
2
4
6
8
10
*10^6
energy (eV)
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_1
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_2
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_n_3
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
neutron energy (eV)
20
*10^6


Energy distribution (CMS)
n_n_4
probability
10^{-1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_5
probability
10^{-1}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_6
probability
10^{1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (CMS)
n_n_7
probability
10^{1}
0
energy (eV)
5
10
15
20
*10^6
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_n_cont part.=neutron
probability
10^0
10^-2
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_n_cont part.=gamma
probability
10^{0}
10^{-2}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_p_tot part.=proton
probability
10^1
10^-1
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_p_tot part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_a_tot part.=alpha
probability
10^0
10^-2
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Energy distribution (LABS)
n_a_tot part.=gamma
probability
10^{2}
10^{0}
10^{-2}
0
5
10
15
20
*10^6
energy (eV)
0
5
10
15
20
*10^6
neutron energy (eV)


Gamma energy distribution
Capture
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
5
10
15
20
*10^6


Gamma angles distribution
Capture
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
neutron energy (eV)
*10^6

Gamma multiplicities distribution
Capture




Gamma energy distribution
n_n_1
probability
100
50
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_1
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_1




Gamma energy distribution
n_n_2
probability
100
50
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_2
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_2




Gamma energy distribution
n_n_3
probability
100
50
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_3
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_3




Gamma energy distribution
n_n_4
probability
100
50
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_4
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_4




Gamma energy distribution
n_n_5
probability
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_5
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_5




Gamma energy distribution
n_n_6
probability
100
80
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
0
5
10
15
20
*10^6


Gamma angles distribution
n_n_6
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_6




Gamma energy distribution
n_n_7
probability
100
80
60
40
20
0
gamma energy (MeV)
0
5
10
15
20
neutron energy (eV)
5
10
15
20
*10^6


Gamma angles distribution
n_n_7
probability
10^0
1.0
0.5
0.0
-0.5
-1.0
cos(theta)
0
5
10
15
20
*10^6
neutron energy (eV)

Gamma multiplicities distribution
n_n_7