

Ordinate Scales are Relative Standard Deviation (%) and barns

Abscissa Scales are Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scales are Relative Standard Deviation (%) and barns

Abscissa Scales are Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scales are Relative Standard Deviation (%) and barns

Abscissa Scales are Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scales are Relative Standard Deviation (%) and barns

Abscissa Scales are Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)









Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scales are Relative Standard Deviation (%) and barns

Abscissa Scales are Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scales are Relative Standard Deviation (%) and barns

Abscissa Scales are Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scales are Relative Standard Deviation (%) and barns

Abscissa Scales are Energy (eV)









Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scales are Relative Standard Deviation (%) and barns

Abscissa Scales are Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scales are Relative Standard Deviation (%) and barns

Abscissa Scales are Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scales are Relative Standard Deviation (%) and barns

Abscissa Scales are Energy (eV)





Correlation Matrix





Ordinate Scale is
Relative Standard Deviation (%)

Abscissa Scales are
Energy (eV)





Correlation Matrix





Ordinate Scales are Relative Standard Deviation (%) and barns

Abscissa Scales are Energy (eV)





Correlation Matrix