




H factor -  $E_{\text{int}}$ (20-150 MeV)




H factor - (Full energy range, MeV)




R factor -  $E_{\text{int}}$ (20-150 MeV)




R factor - (Full energy range, MeV)




F factor -  $E_{\text{int}}$ (20-150 MeV)




F factor - (Full energy range, MeV)




S factor -  $E_{\text{int}}$ (20-150 MeV)




S factor - (Full energy range, MeV)




M factor -  $E_{int}$ (20-150 MeV)




M factor - (Full energy range, MeV)




P1.3 factor -  $E_{\text{int}}$ (20-150 MeV)




P1.3 factor - (Full energy range, MeV)




P2 factor -  $E_{int}(20-150 \text{ MeV})$



P2 factor - (Full energy range, MeV)



P10 factor -  $E_{int}(20-150 \text{ MeV})$



P10 factor - (Full energy range, MeV)

