























































$^{238}\text{U}(p,x)\text{K}$  $^{238}\text{U}(p,x)\text{Ca}$  $^{238}\text{U}(p,x)\text{Sc}$  $^{238}\text{U}(p,x)\text{Ti}$  $^{238}\text{U}(p,x)\text{V}$  $^{238}\text{U}(p,x)\text{Cr}$  $^{238}\text{U}(p,x)\text{Mn}$  $^{238}\text{U}(p,x)\text{Fe}$  $^{238}\text{U}(p,x)\text{Co}$ 










$^{238}\text{U}(p,x)\text{Ni}$  $^{238}\text{U}(p,x)\text{Cu}$  $^{238}\text{U}(p,x)\text{Zn}$  $^{238}\text{U}(p,x)\text{Ga}$  $^{238}\text{U}(p,x)\text{Ge}$  $^{238}\text{U}(p,x)\text{As}$  $^{238}\text{U}(p,x)\text{Se}$  $^{238}\text{U}(p,x)\text{Br}$  $^{238}\text{U}(p,x)\text{Kr}$ 









$^{238}\text{U}(p,x)\text{Rb}$  $^{238}\text{U}(p,x)\text{Sr}$  $^{238}\text{U}(p,x)\text{Y}$  $^{238}\text{U}(p,x)\text{Zr}$  $^{238}\text{U}(p,x)\text{Nb}$  $^{238}\text{U}(p,x)\text{Mo}$  $^{238}\text{U}(p,x)\text{Tc}$  $^{238}\text{U}(p,x)\text{Ru}$  $^{238}\text{U}(p,x)\text{Rh}$ 

$^{238}\text{U}(p,x)\text{Pd}$  $^{238}\text{U}(p,x)\text{Ag}$  $^{238}\text{U}(p,x)\text{Cd}$  $^{238}\text{U}(p,x)\text{In}$  $^{238}\text{U}(p,x)\text{Sn}$  $^{238}\text{U}(p,x)\text{Sb}$  $^{238}\text{U}(p,x)\text{Te}$  $^{238}\text{U}(p,x)\text{I}$  $^{238}\text{U}(p,x)\text{Xe}$ 



$^{238}\text{U}(p,x)\text{Gd}$  $^{238}\text{U}(p,x)\text{Tb}$  $^{238}\text{U}(p,x)\text{Dy}$  $^{238}\text{U}(p,x)\text{Ho}$  $^{238}\text{U}(p,x)\text{Er}$  $^{238}\text{U}(p,x)\text{Tm}$  $^{238}\text{U}(p,x)\text{Yb}$  $^{238}\text{U}(p,x)\text{Lu}$  $^{238}\text{U}(p,x)\text{Hf}$ 

$^{238}\text{U}(p,x)\text{Ta}$  $^{238}\text{U}(p,x)\text{W}$  $^{238}\text{U}(p,x)\text{Re}$  $^{238}\text{U}(p,x)\text{Os}$  $^{238}\text{U}(p,x)\text{Ir}$  $^{238}\text{U}(p,x)\text{Pt}$  $^{238}\text{U}(p,x)\text{Au}$  $^{238}\text{U}(p,x)\text{Hg}$  $^{238}\text{U}(p,x)\text{Tl}$ 

$^{238}\text{U}(p,x)\text{Pb}$  $^{238}\text{U}(p,x)\text{Bi}$  $^{238}\text{U}(p,x)\text{Po}$  $^{238}\text{U}(p,x)\text{At}$  $^{238}\text{U}(p,x)\text{Rn}$  $^{238}\text{U}(p,x)\text{Fr}$  $^{238}\text{U}(p,x)\text{Ra}$  $^{238}\text{U}(p,x)\text{Ac}$  $^{238}\text{U}(p,x)\text{Th}$ 