




H factor - E_{low} (0-20 MeV)




H factor - E_{int} (20-150 MeV)




H factor - E_{high} (150+ MeV)




H factor - (Full energy range, MeV)




R factor - E_{low} (0-20 MeV)




R factor - E_{int} (20-150 MeV)







R factor - E_{high} (150+ MeV)




R factor - (Full energy range, MeV)







S factor - E_{low} (0-20 MeV)




S factor - E_{int} (20-150 MeV)




S factor - E_{high} (150+ MeV)




S factor - (Full energy range, MeV)




M factor - E_{low} (0-20 MeV)



M factor - E_{int} (20-150 MeV)



M factor - E_{high} (150+ MeV)



M factor - (Full energy range, MeV)

