




R factor - E_{low} (0-20 MeV)




R factor - E_{int} (20-150 MeV)




R factor - E_{high} (150+ MeV)




R factor - (Full energy range, MeV)




F factor - E_{low} (0-20 MeV)




F factor - E_{int} (20-150 MeV)




F factor - E_{high} (150+ MeV)




F factor - (Full energy range, MeV)




S factor - E_{low} (0-20 MeV)




S factor - E_{int} (20-150 MeV)











S factor - E_{high} (150+ MeV)




S factor - (Full energy range, MeV)









P2 factor - E_{low} (0-20 MeV)



P2 factor - E_{int} (20-150 MeV)



P2 factor - E_{high} (150+ MeV)



P2 factor - (Full energy range, MeV)

